

## Discontinued Models of Laser Beam Machines

\*Regarding substitute models, there may be minor specification differences, so please consult us before placing an order.

\*Parts that become unprocurable may not be able to be supplied even before the parts supply end date.

Discontinued Model	Discontinued Date	Parts supply end	Substitute Model
LM-305C	—	—	No substitute model available
LM-305CS	—	—	No substitute model available
LM-P2	—	—	No substitute model available
LX-007-048	—	—	No substitute model available
LX-015-048	—	—	No substitute model available
LX-015048A	—	—	No substitute model available
LX-015048B	—	—	No substitute model available
LX-015048E	—	—	No substitute model available
LX-015-510	—	—	No substitute model available
LX-015510A	—	—	No substitute model available
LX-015510B	—	—	No substitute model available
LX-015510E	—	—	No substitute model available
LX-015CH	—	—	No substitute model available
LX-020-510	—	—	No substitute model available
LX-020510A	—	—	No substitute model available
LX-020510B	—	—	No substitute model available
LX-020510M	—	—	No substitute model available
LX-AP1	—	—	No substitute model available
LX-AP10	—	—	No substitute model available
LX-AP10E	—	—	No substitute model available
LX-AP20	—	—	No substitute model available
LX-AP20-01	—	—	No substitute model available
LX-AP20-02	—	—	No substitute model available
LX-AP20S	—	—	No substitute model available
LX-AP30	—	—	No substitute model available
LX-APDA2	—	—	No substitute model available
LXH-15510	Mar. 2001	Mar. 2011	No substitute model available